



ITC-Aerospace, Inc.

NAX Bldg., 7Fl., 1-3-2, Shinkawa, Chuo-Ku, Tokyo 104-0033 Japan

E-mail ; itc-group@itca.co.jp URL; www.itca.co.jp

1991 Aerospatiale AS350B



Equipment Specifications	
Production Year	1991
Manufacturer	Aerospatiale
Model	AS350B
Price	Call
Location	Japan
Condition	Pre-Owned
Serial Number	TBD
Airframe Total Time	2,483+45 hrs
Engine	Arriel 1B S/N 4336 TSN 2,475 hrs (TBO 3,000hrs)

ITC-Aerospace, Inc. Tokyo, Japan

Tel : +81-3-3555-3621 FAX : +81-3-3555-3627



General Information
<p>Aircraft Total Time: 2,483+45 hrs Engine: Arriel 1B Serial No. 4336 Engine Total Time: 2,475 hrs (TBO 3,000 hrs)</p>
<p>Features: Corporate configuration with VIP leather finish</p>
<p>Special Equipments: TBD</p>
<p>Avionics Horizontal Gyro Indicator : AIM500DCF Directional Gyro Indicator : AIM200DC DAT Indicator : K150 Stand-By Compass : KCA0113W VOR Receiver : KN-53 VOR Indicator : KI-203 ADF Indicator : KI-227 ADF Receiver : KR-87 ATC Transponder : KT-76A Multiple Indicator : 704A47-270-101 Tachometer-Nr Indicator : 42960-00 Tachometer-Ng 64530-068-4 Torque Meter Indicator : 30573136 Rate of Climb Indicator : SP03401 Air Speed Indicator : 38399-490 Reporting Altimeter : LE-50-1B Clock : AC-1-2A</p>



Further details available upon request by e-mail:
nakayamat@itca.co.jp / k.otsudo@itca.co.jp

Aircraft availability subject to prior sale; specifications may change without prior notice, components remaining time subject to verification prior to purchase by buyer, lessor, and/or lessee.

Any given data may change due to ongoing operation of the Aircraft or any other reason without notice. ITC-Aerospace, Inc. and/or the owner does not guarantee the accuracy, completeness or quality of the information provided, or that it is up-to-date. Liability claims against the ITC-Aerospace, Inc. and/or the owner of the Aircraft in respect of material or immaterial damage caused by the use or non-use of the information offered or by inaccurate or incomplete information are excluded provided that there is no provable intent or gross negligence on ITC's or the owner's part.